

# Epoxy Holiday Serving Board Kit Instructions



#### What You'll Need:

- · Epoxy Holiday Serving Board Kit
- Protective Equipment (gloves & glasses)
- · Plastic sheeting or a silicone mat, to catch drips
- A heat gun for removing any small bubbles and for moving the epoxy around on the board to create your design
- · A razor blade and a scraper















### **STEP 1 - GET EVERYTHING READY**

Lay out your materials.

- Be sure your work surface is level.
- If your work area isn't well ventilated, wear a half-face respirator with vapor cartridges. Safety glasses and gloves protect your eyes and hands.
- Using the blue tape, seal bottom edges of the tray, then use a razor blade to trim around the edges.





#### **STEP 2 - MIX RESIN & HARDENER**

- Combine MakerPoxy Epoxy Resin and Hardener at a 1 to 1 ratio, by volume.
- Combine enough to make a few colors to use on your board
- We recommend starting with 2-3 oz. of each part for a combined 4-6 oz. total.
- Stir very well for at least 3 minutes. Stir slowly to avoid bubbles, scraping the sides of the cup.



#### STEP 3 - DIVIDE THE MIXED EPOXY

Divide clear epoxy into the smaller cups to add pigment.



#### **STEP 4 - ADD PIGMENTS**

Mix in the desired amount of pigment. Start with a small amount - add more, as needed, until you get the color you want.

## STEP 5 - ADD COLORED PIGMENTS ONTO YOUR SERVING TRAY

You can use a heat gun to pop any bubbles and to move the resin around the board. Keep the heat gun moving to prevent overheating the resin.

Make any pattern or color combination that you like! Alternate colors and manipulate them using the heat gun.

Continue until you achieve the desired effect. You can always go over it again entirely or just in certain areas.



### **STEP 6 - FINISHING**

Allow the epoxy to fully cure for at least 36-48 hours before removing the tape along the sides and bottom.

Gently heat any remaining drips with a heat gun and scrape off.



